### Seal Beach Mutual One Operating Budget Year Ended December 31, 2021

844		erage Mon er Apartm		Operating Budget In Dollars					
Apartments	2021	2020	Change	2021	2020	Change			
Electricity	5.73	5.43	0.30	58,033	54,995	3,038			
Telephone	0.04	0.04	0.00	405	405	0			
Water	15.46	15.46	0.00	156,579	156,579	0			
Trash	9.50	8.89	0.61	96,216	90,038	6,178			
<b>Total Utilities</b>	30.73	29.82	0.91	311,233	302,017	9,216			
Management Fee	0.56	0.56	0.00	5,672	5,672	0			
Audit Fees	0.00	0.00	0.00	0	0	0			
Legal Fees	3.55	4.64	(1.09)	35,954	46,994	(11,040)			
Investment Fees	0.00	0.00	0.00	0	0	0			
<b>Total Professional Fees</b>	4.11	5.20	(1.09)	41,626	52,666	(11,040)			
Janitorial Services	0.45	0.35	0.10	4,558	3,545	1,013			
Landscape - Contract	29.34	28.45	0.89	297,156	288,142	9,014			
Landscape - Extras	5.13	4.64	0.49	51,957	46,994	4,963			
Landscape - Trees	1.97	1.97	0.00	19,952	19,952	0			
Painting	0.39	0.54	(0.15)	3,950	5,469	(1,519)			
Pest Control	2.78	2.37	0.41	28,156	24,003	4,153			
Structural Repairs	2.47	3.55	(1.08)	25,016	35,954	(10,938)			
Miscellaneous Services	0.33	0.33	0.00	3,342	3,342	0			
Other Service Contracts	3.33	2.76	0.57	33,726	27,953	5,773			
Escrow Expenses	0.00	0.00	0.00	0	0	0			
Office Supplies	0.02	0.02	0.00	203	203	0			
Standard Service Total Services	11.85	11.31	0.54	120,017	114,548	5,469			
	58.06	56.29	1.77	588,033	570,105	17,928			
State & Federal Taxes	1.08	0.95	0.13	10,938	9,622	1,316			
Property & Liability Insurance		23.35	0.97	246,313	236,489	9,824			
Total Taxes & Insurance	25.40	24.30	1.10	257,251	246,111	11,140			
Operating Expenses	118.30	115.61	2.69	1,198,143	1,170,899	27,244			
Income from Services									
Merchandise Sales	0.00	0.00	0.00	0	0	0			
Laundry Machines	4.15	5.73	(1.58)	42,031	58,033	(16,002)			
<b>Total Services Income</b>	4.15	5.73	(1.58)	42,031	58,033	(16,002)			
Financial Income									
Interest Income	3.61	3.18	0.43	36,562	32,207	4,355			
Interest Income Allocation	0.00	0.00	0.00	0	0	0			
Late Charges	0.15	0.17	(0.02)	1,519	1,722	(203)			
Inspection Fees	2.96	3.46	(0.50)	29,979	35,043	(5,064)			
Miscellaneous	1.48	2.17	(0.69)	14,989	21,978	(6,989)			
Parking Fines	0.05	0.00	0.05	506	0	506			
Total Financial Income	8.25	8.98	(0.73)	83,555	90,950	(7,395)			
Operating Income	12.40	14.71	(2.31)	125,586	148,983	(23,397)			
Net Operating Cost	105.90	100.90	5.00	1,072,557	1,021,916	50,641			
Reserve Funding	104.59	109.10	(4.51)	1,059,286	1,104,964	(45,678)			
<b>Total Mutual Costs</b>	210.49	210.00	0.49	2,131,843	2,126,880	4,963			
Allocated Trust Cost	165.05	163.11	1.94	1,671,626	1,651,978	19,648			
Regular assessment**	375.54	373.11	2.43	3,803,469	3,778,858	24,611			

<sup>\*\*</sup>Property taxes are assessed to the stockholder's unit and are added to the regular assessment and become part of the monthly payment. Accordingly, they are excluded from the operating budget.

### Seal Beach Mutual One Assessment And Reserve Funding Disclosure Summary

- 1) The current regular assessment per ownership interest per month is \$ 375.54 and the portion allocated to reserves per ownership interest per month is \$ 94.88 .
- 2) Neither the board nor the members have approved additional assessments for any purpose.
- 3) Based upon the most recent reserve study and other information available to the board of directors, will currently projected reserve account balances be sufficient at the end of each year to meet the association's obligation for repair and/or replacement of major component during the next 30 years?

Yes \_\_\_ X \_\_\_ No \_\_\_\_

- 4) If the answer to #3 is no, what additional assessments or other contributions to reserves would be necessary to ensure that sufficient reserve funds will be available each year during the next 30 years that have not yet been approved by the board or the members?
- 5) No major components, were omitted from the reserve study, and none are excluded from the existing reserve funding:
- 6) Based on the method of calculation in paragraph (4) of subdivision (b) of Section 5570, the estimated required amount to be in the reserve fund at the end of the 2020 fiscal year is \$ 5,020,467 based in whole or in part on the last reserve study or update prepared by the board as of 9/25/2020. The projected reserve fund cash balance at the end of the 2020 fiscal year is \$ 3,851,251 in reserves being 76.7% funded at this date.
- 7) Based on the method of calculation in paragraph (4) of subdivision (b) of Section 5570, the estimated required amount to be in the reserve fund, the projected fund balance of those years, taking into account only assessments approved and the other known revenues, and the percentage funded at the end of each of the next five years is:

	Required	Projected	
Year	Funding	Fund Bal.	% Funded
2021	\$ 3,075,036	3,056,207	99.4%
2022	2,900,410	2,881,577	99.4%
2023	3,757,044	3,738,208	99.5%
2024	4,627,357	4,608,517	99.6%
2025	5,539,537	5,520,693	99.7%

This financial representation set forth in this summary is based on the best estimates of the board at this time and is further predicated on the board maintaining the current Reserve Funding Plan.

## Seal Beach Mutual One Replacement Reserve Summary Budget Year 2021

While preparing the annual operating budget, the board reviews the conditions and assumptions regarding the common interest of the Mutual. This review consists of updating the replacement cost and remaining useful life of the Mutual's common interest property. This data is used to develop reserve requirements using the formula set forth in Civil Code 5570 (b) (4). The board expects to finance all replacements through regular assessments to the shareholders. Accordingly, the board does not plan any special assessments.

		Estimat	ed	Reserve Funding								
	Useful	Remaining	Replacement	Required	Estimated	Planned 2021	Estimated					
Fund	Life	Life	Cost	Funding	Beg. Bal.	Funding	% Funded					
Paint	5 - 10	0 - 4	916,500	900,000	697,599	80,000	86.4%					
Roof	18 - 25	13 - 20	4,934,500	1,277,125	418,756	50,000	36.7%					
Infrastructure	1 - 100	0 - 46	7,940,300	2,843,342	2,734,896	830,956	125.4%					
Total			13,791,300	5,020,467	3,851,251	960,956	95.9%					

### **Seal Beach Mutual One**

## Project Listing for Budget Year - Based on Fully Funded Balance page 14 of the Reserve Study Dated 9/17/2020 2021

**Painting Reserve Projects** 

		Unit	E	Base Line	Year	Repl	epl Yrs. In Us		Years	Fnding	Required	Est.	Surplus/	%
Description	#	Cost	Year	Cost	Acqurd	Year	Serv.	Life	Left	Ratio	Balance	Beg Bal	(Deficit)	Funded
Laundry Rooms Repaint	18	750	2021	13,500	2011	2021	10	10	0	100.00%	13,500	10,464	(3,036)	
Light Poles Repaint	385	86	2021	33,000	2017	2025	4	8	4	50.00%	16,500	12,789	(3,711)	
Stucco Repaint	128	2,891	2021	370,000	2011	2021	10	10	0	100.00%	370,000	286,791	(83,209)	
Wood Surfaces Repaint	108	4,630	2021	500,000	2016	2021	5	5	0	100.00%	500,000	387,555	(112,445)	
Set aside for painting				916,500						_	900,000	697,599	(202,401)	

**Roofing Reserve Projects** 

		Unit	В	Base Line	Year	Repl	Yrs. In	Useful	Years	Fnding	Required	Est.	Surplus/	%
Description	#	Cost	Year	Cost	Acqurd	Year	Serv.	Life	Left	Ratio	Balance	Beg Bal	(Deficit)	Funded
Laundry Room Roofs	18	1,889	2021	34,000		2039				0.00%	0	0	0	
Apartment Roofs (2014)	26	53,846	2021	1,400,000	2014	2039	7	25	18	28.00%	392,000	128,533	(263,467)	
Apartment Roofs (2015)	41	63,415	2021	2,600,000	2015	2040	6	25	19	24.00%	624,000	204,603	(419,397)	
Apartment Roofs (2016)	3	61,667	2021	185,000	2016	2041	5	25	20	20.00%	37,000	12,132	(24,868)	
Carport Roofs (2014)	7	37,143	2021	260,000	2014	2034	7	20	13	35.00%	91,000	29,838	(61,162)	
Carport Roofs (2015)	11	35,000	2021	385,000	2015	2035	6	20	14	30.00%	115,500	37,871	(77,629)	
Carport Roofs (2016)	2	35,250	2021	70,500	2016	2036	5	20	15	25.00%	17,625	5,779	(11,846)	
Set aside for roofing				4,934,500							\$ 1,277,125	\$ 418,756	\$ (858,369)	

**Infrastructure Reserve Projects** 

		J												
		Unit	1	Base Line	Year	Repl	Yrs. In	Useful	Years	Fnding	Required	Est.	Surplus/	%
Description	#	Cost	Year	Cost	Acqurd	Year	Serv.	Life	Left	Ratio	Balance	Beg Bal	(Deficit)	Funded
Elastomeric Flr Resurface	18	2,861	2021	51,500	2012	2032	9	20	11	45.00%	23,175	22,291	(884)	
Concrete - Repair	1	100,000	2021	100,000		2021				100.00%	100,000	96,186	(3,814)	1
Pole Lights - Replace	340	694	2021	236,000	2017	2042	4	25	21	16.00%	37,760	36,320	(1,440)	1
Meter Doors Replacement	67	813	2021	54,500	2019	2044	2	25	23	8.00%	4,360	4,194	(166)	1
Utility Doors Replacement	85	800	2021	68,000	2002	2022	19	20	1	95.00%	64,600	62,136	(2,464)	1
Laundry Water Heaters (<20	20	4,000	2021	80,000	2014	2029	7	15	8	46.67%	37,333	35,909	(1,424)	1
Laundry Water Heaters (201	16	4,000	2021	64,000	2020	2035	1	15	14	6.67%	4,267	4,104	(163)	i

### **Seal Beach Mutual One**

## Project Listing for Budget Year - Based on Fully Funded Balance page 14 of the Reserve Study Dated 9/17/2020 2021

**Infrastructure Reserve Projects, continued** 

			F	Base Line	Year	Repl	Yrs. In	Useful	Years	Fnding	Required	Est.	Surplus/	%
Description		Cost	Year	Cost	Acqurd	Year	Serv.	Life	Left	Ratio	Balance	Beg Bal	(Deficit)	Funded
Clay Lines - Replace	18	36,389	2021	655,000		2062			41	59.00%	386,450	371,711	(14,739)	
Sewer Re-lining (2021)	35	18,000	2021	630,000		2021			0	100.00%	630,000	605,972	(24,028)	
Sewer Re-lining (2022)	35	27,000	2021	945,000		2022			1	96.67%	913,500	878,659	(34,841)	
Sewer Re-lining (2050)	35	45,000	2021	1,575,000		2050			29	3.33%	52,500	50,498	(2,002)	
Repiping Prject (2015)	23	43,478	2021	1,000,000		2065			44	12.00%	120,000	115,423	(4,577)	
Repiping Prject (2016)	36	43,056	2021	1,550,000		2066			45	10.00%	155,000	149,088	(5,912)	
Repiping Prject (2017)	11	47,273	2021	520,000		2067			46	8.00%	41,600	40,013	(1,587)	
Laundry Counters Replaced	35	629	2021	22,000	2004	2024	17	20	3	85.00%	18,700	17,987	(713)	
Irrigation Controllers Repla	18	1,389	2021	25,000	2012	2024	9	12	3	75.00%	18,750	18,035	(715)	
Trees - Trim/Remove/Repl	1	17,500	2021	17,500		2021			0	100.00%	17,500	16,833	(667)	
Wood Repairs	108	1,157	2021	125,000	2016	2021	5	5	0	100.00%	125,000	120,232	(4,768)	
Gutters/Downspouts (2039)	26	2,250	2021	58,500	2014	2039	7	25	18	28.00%	16,380	15,755	(625)	
Gutters/Downspouts (2040)	41	2,220	2021	91,000	2015	2040	6	25	19	24.00%	21,840	21,007	(833)	
Gutters/Downspouts (2041)	3	2,267	2021	6,800	2016	2041	5	25	20	20.00%	1,360	1,308	(52)	
Attic Screens - Replace	280	129	2021	36,000	1993	2023	28	30	2	93.33%	33,600	32,318	(1,282)	
Signage - Replace	1	29,500	2021	29,500	2011	2026	10	15	5	66.67%	19,667	18,917	(750)	
Set aside for infrastructure		•		7,940,300		•	•				2,843,342	\$2,734,896	(108,446)	

**3 3** 

**Totals** 

13,791,300

\$ 5,020,467 | \$3,851,251 | \$(1,169,216) | 76.7%

<sup>\*</sup> The Mutual's 70 residential buildings are divided into separate clusters consisting of four buildings each. In the center of each building cluster is a laundry room. The building cluster and laundry room are considered a homogenous unit in determining the necessity and timing for painting and roofing.

## Seal Beach Mutual One Reserve Contributions Work Sheet Budget Year 2021

	Estimated	Current						
	Remaining	Replacement	Reserv	e Balance	Annual	Per Unit		
Fund	Life	Cost	Required	Est. Beg. Bal.	Contribution	Per M	Ionth	
Appliance	Note (1)	177,198	177,198	89,550	87,648	\$	8.65	
Painting	0 - 4	916,500	900,000	697,599	80,000	Note (2)		
Roofing	13 - 20	4,934,500	1,277,125	418,756	50,000	Note (3)		
Infrastructure	0 - 46	7,940,300	2,843,342	2,734,896	830,956	Note (4)		
Contribution	n to the Replace	ement funds	5,020,467	3,851,251	960,956	\$	94.88	
Contingonory				227 706	5 241	Note (5)		
Contingency				337,706	<i>'</i>	Note (5)		
Emergency				400,194		Note (6)		
	,	Total for budget		4,678,701	1,059,286	\$	104.59	

Project Reserve Contribution Comparison										
Project	2021	2020	Change	Chg PAPM						
Appliance	87,648	144,008	(56,360)	(5.56)						
Painting	80,000	80,000	ı	-						
Roofing	50,000	50,000	ı	-						
Infrastruct	830,956	830,956	1	-						
Operating	5,341	-	5,341	0.53						
Emergency	5,341	-	5,341	0.53						
Total	1,059,286	1,104,964	(45,678)	(4.51)						

#### **Notes:**

- 1) The appliance fund is used to fund the replacement of appliances and fixtures. The value of this fund is calculated annually and is the five-year average units replaced times the current replacement cost adjusted for planned expenditures during the budget year. Current installed replacement cost for this calculation is \$241,905 and the adjustment is a \$64,707 decrease for a total requirement of \$177,198. The board approved the 2021 funding of this reserve for \$87,648.
- 2) The board determined funding of \$80,000 for 2021.
- 3) The board determined funding of \$50,000 for 2021.
- 4) The board determined funding of \$830,956 for 2021.
- 5) The board determined funding of 5,341 for 2021.
- 6) The board determined funding of 5,341 for 2021.

### Seal Beach Mutual One Appliance Replacement History

														Uni	t	Insta	lled Cost
Item	2019	2018	2017	2016	2015	2014	2013	2012	2011	2010	2009	2008	2007	Total	5 yr ave.	Unit Cost	Extended
Cooktops	7	25	18	23	8	10	13	4	3	7	6	7	8	139		\$ 520	\$ 8,323
Ovens	36	42	49	45	23	42	20	20	12	16	10	15	16	346	39	1,147	44,727
Refrigerators	57	57	51	50	51	45	39	38	18	38	31	36	37	548	53	1,126	59,686
Hot Water Heaters	10	6	62	185	69	27	9	35	49	181	83	80	27	823	66	778	51,366
Garbage Disposals	34	20	25	28	27	16	22	39	14	21	16	27	26	315	27	233	6,289
Sinks - Bath	12	9	14	18	10	9	7	3	1	7	2	7	9	108	13	156	2,032
Sinks - Kitchen	15	14	26	8	10	13	9	4	4	8	4	15	13	143	15	662	9,931
Counters - Bath	4	4	3	4	3	2	2	0	0	3	0	3	4	32	4	624	2,495
Counters - Kitchen	10	7	12	13	6	6	21	0	2	6	2	7	8	100	10	1,470	14,702
Bath Heaters and Fan	28	55	14	9	9	20	10	16	6	9	11	14	10	211	23	538	12,364
Toilets	26	73	36	31	24	23	32	10	3	18	3	19	13	311	38	275	10,467
Faucet - Bath	19	18	21	39	14	21	14	9	4	14	4	13	8	198	22	143	3,142
Faucet - Kitchen	13	42	40	54	40	47	38	18	16	25	19	37	48	437	38	191	7,259
Hot Water Tanks - Laund	1	0	1	0	1	1	0	1	1	0	1	3	0	10	1	833	833
Washers	0	1	5	9	9	6	7	2	3	10	4	3	5	64	5	936	4,679
Dryers	0	0	7	17	3	8	4	6	8	14	7	3	9	86	5	722	3,610
Estimated replacement cost based	d on a	verag	ge rep	olacei	ment	histo	ory w	ith cu	ırrent	unit	cost	s - 20	)15 t	o 2019	x cu	rrent prici	\$ 241,905

Adjustment based on projected expenditures for 2021 \$ (64,707) Combined current and contingent appliance replacements \$ 177,198

Appliances can be billed on bill codes o	ther
than replacement. As such, total replace	ment
expenditures to the right may be less that	an the
total value of replacement items listed a	bove.

tual expenditures:	
2019	123,828
2018	137,512
2017	149,610
2016	220,684
2015	106,722
2014	90,435
2013	63,705
2012	94,411
5 yr average	\$ 147,671

# SEAL BEACH MUTUAL ONE FLOW OF RESERVE FUNDS

	Beginning	Annual	Interest*	Loans or		Ending
Year	Fund	Funding	0.00%	Assessments	Expenses	Fund
2020					·	3,851,251
2021	3,851,251	960,956	0		1,756,000	3,056,207
2022	3,056,207	989,785	0		1,164,415	2,881,577
2023	2,881,577	1,019,479	0		162,848	3,738,208
2024	3,738,208	1,050,063	0		179,754	4,608,517
2025	4,608,517	1,081,565	0		169,389	5,520,693
2026	5,520,693	1,114,012	0		894,959	5,739,746
2027	5,739,746	1,147,432	0		140,301	6,746,877
2028	6,746,877	1,181,855	0		144,510	7,784,222
2029	7,784,222	1,217,311	0		250,187	8,751,346
2030	8,751,346	1,253,830	0		153,311	9,851,865
2031	9,851,865	1,291,445	0		1,513,251	9,630,059
2032	9,630,059	1,330,188	0		233,935	10,726,312
2033	10,726,312	1,370,094	0		214,577	11,881,829
2034	11,881,829	1,411,197	0		554,371	12,738,655
2035	12,738,655	1,453,533	0		856,882	13,335,306
2036	13,335,306	1,497,139	0		1,305,577	13,526,868
2037	13,526,868	1,542,053	0		188,553	14,880,368
2038	14,880,368	1,588,315	0		194,210	16,274,473
2039	16,274,473	1,635,964	0		2,740,917	15,169,520
2040	15,169,520	1,685,043	0		4,924,722	11,929,841
2041	11,929,841	1,735,594	0		2,492,977	11,172,458
2042	11,172,458	1,787,662	0		784,114	12,176,006
2043	12,176,006	1,841,292	0		225,142	13,792,156
2044	13,792,156	1,896,531	0		540,763	15,147,924
2045	15,147,924	1,953,427	0		238,853	16,862,498
2046	16,862,498	2,012,030	0		1,554,630	17,319,898
2047	17,319,898	2,072,391	0		253,399	19,138,890
2048	19,138,890	2,134,563	0		316,534	20,956,919
2049	20,956,919	2,198,600	0		344,334	22,811,185
2050	22,811,185	2,264,558	0		4,139,308	20,936,435
Totals		45,717,907	0	0	28,632,723	

<sup>\*</sup> Interest earned on the fund is currently not reinvested in the fund.